

NOTES:

1. ANY CHANGES IN PLANS SUCH AS DEEPER FLOOR JOISTS OR CHANGES IN CEILING HEIGHTS EGT. THAT CAN AFFECT FLOOR TO FLOOR HEIGHTS CAN EFFECT STAIR CONFIGURATION AND SHOULD BE THOROUGHLY REVIEWED BEFORE PROCEEDING WITH CONSTRUCTION.
2. PROVIDE THROUGH FLASHING AROUND ALL WINDOWS AND DOORS AND AT ALL ROOF JUNCTIONS. -TYPICAL
3. BLOCK AROUND ALL WINDOWS FOR SHUTTER HARDWARE.

MINIMUM TOTAL R-VALUES:

CATHEDRAL CEILING	R-23
CEILING	R-31
WALLS	R-16
FLOORS	R-20

