

1) ROOF - MECHANICAL - AREA D 1/8" = 1'-0"

**GENERAL NOTES: ROOF** 

<u>KEYNOTES</u>

- MAINTAIN ALL MANUFACTURER'S CLEARANCES ON ALL EQUIPMENT.
   SPILL UNIT CONDENSATE TO NEAREST ROOF DRAIN. SIZE CONDENSATE PIPE PER MANUFACTURER'S RECOMMENDATIONS.
   REFER TO SHEETS M403 AND M404 FOR ROOFTOP UNIT DETAILS.

EXHAUST FAN INSTALLED ON 18" TALL CURB. TRANSITION DUCTWORK TO FAN OPENING AS REQUIRED. MAKE-UP AIR UNIT INSTALLED ON A FULL PERIMETER CURB.

MAKE-UP AIR UNIT INSTALLED ON A FULL PERIMETER CURB.
ROUTE THE REFRIGERANT PIPING DOWN THROUGH A NEW
ROOF CURB/PIPING PORTAL. PROVIDE A ROOF PRODUCTS
MODEL RPPC-90 ROOF CURB WITH PIPE CHASE. REFER TO
THE PIPE PORTAL DETAIL ON SHEET M602 FOR ADDITIONAL
INFORMATION. ROOF CURB SHALL BE 3'-0" AWAY FROM
CONDENSING UNIT. REFRIGERANT PIPING SHALL BE
SUPPORTED BY COOPER B-LINE C-SERIES ROOFTOP
SUPPORTS.

CONDENSING UNIT MOUNTED ON A ROOF CURB. REFER TO DETAIL ON SHEET M602. ROOF HYDRANT; REFERENCE PLUMBING DRAWINGS FOR ADDITIONAL DETAIL. DUCTWORK DOWN TO FLOOR BELOW. REFER TO SHEET M114

M13 DUCTWORK DOWN TO FLOOR BELOW. REFER TO SHEET M124

FOR CONTINUATION.

200 E Market Street Charactesville, VA 22902 434,296,5684

VMDO Architects




VMDO



## PAUL VI CATHOLIC HIGH SCHOOL

CATHOLIC DIOCESE OF ARLINGTON 200 North Glebe Road Arlington, VA 22203 Loudoun County ZCPA Number

VMDO Project Number





Checked By

CMG


2016-0005

<u> 15.1188</u>





TRUE NORTH



ISSUES AND REVISIONS NO. SUBMITTAL

ROOF PLAN - AREA D -MECHANICAL